



Nampa Airport • 100 N. Kings Rd. • Nampa, ID 83687 • (208) 466-1711 • FAX (208) 466-7194

## SERVICE BULLETIN LETTER #42A

DATE:

C

SUBJECT:

Correction To Service Bulletin #42, Fuel Valve Leaking

APPLICABILITY:

All Kitfoxes Equipped with P/N 46018.000 or 47012.000 Fuel Valves

COMPLIANCE:

**MANDATORY** 

FROM:

Skystar Aircraft Engineering

Service Bulletin #42 read "APPLICABILITY: All Kitfoxes Equipped with the P/N 49001.000 fuel valve."

This bulletin changes the applicable part numbers to P/N 46018.000 and 47012.000.

Prior to your next flight, perform an inspection of your fuel valve for evidence of fuel leakage. Pay particular attention to the plugs, either pressed in or screwed into the side of the valve body, and to the swaged fittings on the hoses that are attached to the valve. Repeat this inspection at frequent intervals to guard against the leakage of fuel into the cockpit.

Any evidence of leakage is sufficient to conclude that the valve is deteriorating and should be replaced.

We no longer stock or ship these valves, and have developed a replacement fuel valve kit, P/N 10251.000 that can be ordered by calling Customer Service at 208-466-1711. Replacement of the old valve that shows any signs of leakage is mandatory before further flight, and precautionary replacement of the old valve is recommended.

-----

From: Sally Miller

To: Carl Cederquist, Dave Morris, Gib Boren, Mark Budak, Terri Taylor, Terry

Bush

Subject: Service Bulletin 42 (fwd)

ERROR on Service Bulletin 42:

The P/N 49001.000 Fuel Valve is incorrect, it should be P/N 46018.000.

## Thanks Skip!

=Fwd by: Mark Budak==== 9/26/94 8:58am=
Fwd to: Sally Miller

By the by, there was also a P/N 47012.000 fuel valve that was used, which was identical to the 46018.000 valve except for the hose fittings provided with the valve. Therefore, the bulletin should also apply to the P/N 47012.000 valve, since the valve body is identical to the P/N 46018.000 valve and subject to the same leakage problems.

=Fwd by: Sally Miller== 9/26/94 9:04am= Fwd to: Carl Cederquist, Dave Morris, Eric Krueger, Frank Miller, Gib Boren, Mark Budak, Terri Taylor, Terry Bush

Thanks Mark!

Revision Date: September 26, 1994

## PART NUMBER ASSIGNMENT/CHANGE FORM

Initiated by: SALLY MILLER	Date:			
Part Number: <u>00201.042</u> New M				
Description: (30 Character Limit)				
SERVICE BULL	ETIN 42A			
Unit Description: EACIA Decimal P.	laces (0,1,2,3) Supplier:			
Cost per Unit: List				
	m Weight:			
	Number Per Plane:			
	****			
Comments: RE-DO 4Z				
General Ledger Inventory Account:	0-000-1300			
General Ledger Offset Account:	0-000-7190-000			
General Ledger Cost of Goods Account:	0-000000			
General Ledger Sales Account:	0-000-6100			
General Ledger Discount Account:	0-000-6150-100			
General Ledger Returns Account:	0-000-6100			
Receipts:	0-000-1300			
Component Breakdown:				
TRACKING:				
Engineering Initials Date	Inventory Init Date			
Other Date	C/S Date Weight Date			
General Manager Date	Price ( ) Date			
Pop Up Date	PNAF ( ) Date			