



Nampa Airport • 100 N. Kings Rd. • Nampa, ID 83687 • (208) 466-1711 • FAX (208) 466-7194



SERVICE LETTER #40

DATE: November 19, 1994

SUBJECT: Bridge Rectifier

APPLICABILITY: All Models

COMPLIANCE: As required

FROM: SkyStar Engineering

Field experience has shown that installation of the optional bridge rectifier to power an hourmeter, when wired in accordance with the schematic in the assembly manual, can sometimes adversely effect the operation of the charging system. Therefore, the bridge rectifier is being omitted from the schematic. A seperate wiring diagram will be furnished to those builders ordering the bridge rectifier option. If you have any questions regarding the current installation of your bridge rectifier, please call SkyStar Technical Support at 208-466-1711.